



QUICK TURN

		QUICK TURN 100MS	QUICK TURN 100MSY	QUICK TURN 100MY	QUICK TURN 200MA		QUICK TURN 200MB		QUICK TURN 200MSY	QUICK TURN 200MY	
Bed Length					500U	1000U	500U	1000U	500U	500U	1000U
Capacity	Maximum Swing(mm)	550	550	550	660	660	695	695	695	695	695
	Maximum Machining Diameter (mm)	280	280	280	360	360	380	380	380	380	380
	Maximum Bar Work Capacity (mm)	52	52	52	65	65	65	65	65	65	65
	Maximum Machining Length (mm)	409	409	340	535	1,055	541	1,047		555	1,020
Main Spindle	Chuck Size (inch)	6	6	6	8	8	8	8	8	8	8
	Maximum Speed (rpm)	6,000	6,000	6,000	5,000	5,000	5,000	5,000	5,000	5,000	5,000
Second Spindle	Chuck Size (inch)	5	5						6		
	Maximum Speed (rpm)	6,000	6,000						6000		
Turret (Upper)	Number of Tools	12	12	12	12	12	12	12	12	12	12
	Maximum Speed (rpm)	5,000	5,000	5,000	5,000	5,000	5,000	5,000	5,000	5,000	5,000
Feed Axes	Travel (X Axis) mm	187	187	187	225	225	234	234	234	234	234
	Travel (Y Axis) mm		100	100					100	100	100
	Travel (Z Axis) mm	460	510	440	605	1,125	625	1,145	625	625	1,090
	Travel (W Axis) mm		460						585		

QUICK TURN

		QUICK TURN 250MA		QUICK TURN 250MB		QUICK TURN 250MSY	QUICK TURN 250MY	
Bed Length		500U	1000U	500U	1000U	500U	500U	1000U
Capacity	Maximum Swing(mm)	660	660	695	695	695	695	695
	Maximum Machining Diameter (mm)	360	360	380	380	380	380	380
	Maximum Bar Work Capacity (mm)	80	80	80	80	80	80	80
	Maximum Machining Length (mm)			512	512		555	991
Main Spindle	Chuck Size (inch)	10	10	10	10	10	10	10
	Maximum Speed (rpm)	4,000	4,000	4,000	4,000	4,000	4,000	4,000
Second Spindle	Chuck Size (inch)					6		
	Maximum Speed (rpm)					6000		
Turret (Upper)	Number of Tools	12	12	12	12	12	12	12
	Maximum Speed (rpm)	5,000	5,000	5,000	5,000	5,000	5,000	5,000
Feed Axes	Travel (X Axis) mm	225	225	234	234	234	234	234
	Travel (Y Axis) mm					100	100	100
	Travel (Z Axis) mm	605	1,125	625	1,090	625	625	1,090
	Travel (W Axis) mm					585		

