

## VARIAXIS i

		VARIAXIS i-300 AWC	VARIAXIS i-500	VARIAXIS i-600	VARIAXIS i-700	VARIAXIS i-700T	VARIAXIS i-800	VARIAXIS i-800 NEO	VARIAXIS i-800T	VARIAXIS i-1050	VARIAXIS i-1050T
Spindle	Spindle Taper	40	40	40	40	40	50	BT50	BT50	50	50
	Maximum Speed (rpm)	12,000	12,000	12,000	12,000	18,000	10,000	10,000	10,000	10,000	10,000
	Motor Output (30 minute rating) kw		22				37				
Magazine	Number of Tools	145	30	30	30	30	30	30	30	30	30
Rotary Axes	Table Tilt (A axis)	150	150	150	150	150	150	150	160	280	280
	Table Indexing (C axis)	360	360	360	360	360	360	360	360	360	360
Feed Axes	Travel (X Axis) mm	350	350	510	630	630	730	750	730	1,200	1,200
	Travel (Y Axis) mm	550	550	910	1,100	1,100	850	890	850	1,385	1,385
	Travel (Z Axis) mm	510	510	510	600	600	560	600	560	900	900